

5201 Woodmere Drive, Bakersfield, CA 93313-- www.welenco.com--(800) 445-9914 California Contractor's License No. 722373

FULL WAVEFORM SONIC - VDL LOG FILING NO. **UNAVCO** COMPANY _ China Lake NWC B-917 WELL **China Lake FIELD** California San Bernardino COUNTY STATE LOCATION: OTHER SERVICES: **EL-GR HIRAT CALIPER** JOB NO. 8737 SEC: 15 TWP: 29S RGE: 44E LAT.: 35° 24' 19.5" LONG.: 117° 15' 28.3" MERIDIAN.: Mt. Diablo Permanent Datum: Top of Casing 3900 Ft. Elev.: K.B. , Elev._ Ft. **Top of Casing** Log Measured From: Ft. Above Perm. Datum Drilling Measured From: Ground Level G.L. 3900 Ft. Date Jun. 24, 2008 Depth-Driller Ft 610 Ft Depth-Logger Ft Ft Ft 607 Ft Ft Ft Ft Top Logged Interval 400 Btm. Logged Interval 607 Ft Ft Ft Ft Casing-Driller 6 Ft In @ 410 Ft In @ Ft In @ In @ Casing-Logger 6 In @ 415 Ft In @ Ft In @ Ft In @ Ft Bit Size 6 In In In Time On Bottom Type Fluid In Hole Water Density Viscosity Fluid Loss ml ml ml ml N\A Source of Sample N\A Rm @ Measured Temp. @ °F °F N\A °F °F Rmf @ Measured Temp. @ °F @ °F @ @ ۰F Rmc @ Measured Temp. °F °F °F Source Rmf Rm @ BHT @ ۰F @ ۰F @ °F °F @ Time Since Circulation Hr Hr Hr Max. Rec. Temp. °F °F Van No. Location SVG L-18 Recorded By **Mitch Tullis**

Witnessed By

| Miscellaneous Information |
|---|
| A recreational GPS accurate to +/- 45 feet set for Datum NAD27 was used to calculate |
| Latitude, Longitude & Elevation values. The Section, Township, and Range then |
| determined using the TRS program (TRS accuracy is not guaranteed). The TRS |
| program converts Latitude and Longitude to Section, Township, and Range. The |
| NOTICE at the bottom of this heading also applies. |
| |
| |
| |
| |
| |
| |
| |
| |
| |
| |
| |
| |
| |
| |
| |
| |
| |
| |
| |
| |
| |
| |
| |
| |
| |
| |
| |
| |
| |
| |
| |
| |
| |
| |
| |
| |
| NOTICE |
| All interpretations are opinions based on inferences from electrical and other measurements and we do not guarantee the accuracy or correctness of any verbal or written interpretation, and we shall not, except in the case of gross or willful negligence on our part, be liable or responsible for any loss, costs, damages or expenses incurred or sustained by anyone resulting from any interpretation made by one of our officers, agents or employees. These interpretations are also subject to our General Terms and Conditions as set out in our current Price Schedule. welenco, inc. June 24, 2008 |

welenco