
B921 randsb921bcs2008



Top of cement

6" Casing

100 ft 89.1°

bottom of casing


200 ft - very fractured

Encountered basaltic dikes

at 218 - 230 ft and 240 - 245 ft

NOT TO SCALE Cables not shown all depths relative to top of casing

Last updated on June 18, 2008



605 ft - Hit a loose gravelly zone with small rounded granite cobbles T.D. -

620 ft

← 450 ft 88.1°

457 ft

459 ft SEISMOMETER

477.5 ft

500 ft 88.2°

500 - 540 ft - fracture zone

600 ft 86.8°